


The male side of 6 pin molex probably. (pic 3) shows where the problem is most likely. the molex, although male, the contact connections inside the six holes are female-ish (pix 4,5,6). although the open tips get crimped/compressed the first time the connectors are mated, over time with heat, moisture etc. they expand. Intermittent/flaky symptoms are consistent with this kind of fault.

Attached FAQs on removing the control panel and board, so they can get to the connectors.



2-pin Mini-Fit Jr. Molex connectors
(1-male 1-female w/pins)

