Teknatool International Limited

7D Dallan Place, Rosedale, Auckland, New Zealand

Tel: +64 09 477 5600 Fax: +64 477 5601

Email: service@teknatool.com
Website: www.teknatool.com



Frequently Asked Questions

Date Raised: 16 May 2017 Date Amended: 23 Oct 2020 Safe practices should always be employed to ensure the Health and Safety of yourself, employees and customers (if applicable) Refer to product manuals, exploded drawings and our website if further assistance is required, or contact us on service@teknatool.com

How to Enter Service Mode on NOVA DVR Saturn

- 1 Hold down the following keys in this order:
 - 1. <Mode M>
 - 2. <FWD/REV>
 - 3. <UP RPM>



Enter the service password "3210" by tapping <F1> to change the first digit, <F2> to change the second digit and <F3> to change the third digit.

Then press **<ON>** on confirm. You are now in Service mode!



You can check if you are in service mode by pressing **<Program P>** until the parameter "**IR Gain**" shows up. If "IR Gain" is displayed, then you are in service mode.