Teknatool International Limited

7D Dallan Place, Rosedale, Auckland, New Zealand Tel: +64 09 477 5600 Fax: +64 477 5601

Email: service@teknatool.com Website: www.teknatool.com



Frequently Asked Questions

How to remove and replace control panel on NOVA Voyager

Date Raised: 12 February 2018	Safe practices should always be employed to ensure the Health and Safety of yourself, employees and customers (if applicable) Refer to product manuals, exploded drawings and our website if further assistance is required, or contact us on service@teknatool.com			
Date Amended				
To remove or replace the control panel on the NOVA Voyager:				
Required tools:				

Required tools:

1 x Philips Screwdriver	

Procedure:

Ste No	ep o.	Description	Image			
	Removal					
	1.	Unscrew the 4 Philips screws (circled) that hold the control panel to the drill press.				
	2.	Lift the control panel up from the drill press head and observe the two cables that connect the control panel to the head.				

3.	Remove the depth sensor cable and 10- pin ribbon cable from the Human Machine Interface (HMI) panel.	Depth Sensor Cable
	1	Replacing
4.	On the back of the control panel, locate and plug in the depth sensor cable and 10-pin connector the HMI.	Image: Depth
5.	Slide the tabs on top of the control panel into the slots. Ensure the control panel rests properly without falling off.	

6.	Screw the 4 Philips screws to mount the control panel to the drill press.	